



F-PRO 2000

Offliner v2.3

Release Description

FEATURE ENHANCEMENTS

- None.

CORRECTIONS TO ISSUES

- **Minor:** The range for v3ph pickup voltage in 60 VTS function corrected as 1 to 50 Volts
- **Minor:** 24 IT -DTL V/F pickup range is corrected to 1 to 2 PU.

COMPATIBILITY

F-PRO 215 Firmware Versions	v1.9 and earlier
F-PRO 216 Firmware Versions	v1.2 and earlier
F-PRO 235 Firmware Versions	v2.4 and earlier
F-PRO 295 Firmware Versions	v1.4
F-PRO 297 Firmware Versions	v1.0
Microsoft Windows	Windows 7 Professional Windows 10 Professional

Minor releases, designated with a letter suffix (e.g. v3.1a), maintain the same compatibility as the base version (e.g. v3.1=v3.1a).



REVISION HISTORY

v2.2 Rev0 – 2018-03-27

- **Enhancement:** Added F-PRO 297 User Manual v1.0 Rev 1.0



CLASSIFICATION OF CHANGES MADE

The issues fixed in software / firmware upgrades are classified as defined below. While the decision to upgrade installed products is the user's, these classifications provide a guideline for the need and priority of the upgrade.

Critical: Critical changes fix issues/problems that prevent the basic operation of the device and have no workaround. Critical changes merit a product upgrade as soon as possible, if that function is being used under the conditions causing the issue

Major: Major changes fix problems that prevent the basic operation of the device but do have a workaround. Any major changes merit a product upgrade as soon as possible if the function is being used under the conditions causing the issue and a workaround is not acceptable.

Minor: Minor changes fix non vital issues that do not prevent the basic operation of the device and may or may not have a workaround. Product upgrades for such changes are not necessary unless they apply to and are needed by the user.

Feature Enhancement: Feature enhancements add a capability or extend existing capabilities of the product. Upgrades for such changes need be made only if and when that feature enhancement is desired.