



TESLA Model 3000 Disturbance Fault Recorder

Firmware v2.7 Release Description

DESCRIPTION

This firmware update for the TESLA 3000 introduces support for additional AC Current Input Modules P/N 110748 (1A) and P/N 110739 (5A).

ENHANCEMENTS

- Firmware update to introduce support for AC Current Input Modules P/N 110748 (1A) and P/N 110739 (5A). No operational changes. This firmware update is required only when input modules P/N 110748 or P/N 110739 are used with TESLA 3000 in applications requiring maximal input accuracy.

COMPATIBILITY

Compatible TESLA Model 4000 Control Panel Software	v1.3 and above
Compatible with RecordBase Central Station Software	v2.0 and above

ERLPhase Power Technologies Customer Support Contact Information

support@erlphase.com

1-204-477-0591 x227

www.erlphase.com

D01753R02.70